

Changes to Lincoln Standard Plans (LSPs) for 1/2/2018

This list is not intended to be exhaustive or include all of the changes made to the 1/2/2018 LSPs. This is only to highlight some of the changes that have occurred. It is the responsibility of the readers to insure themselves of what the most current version says regarding a particular subject.

LSP INDEX

- LSP 81 Fiber Marker and Pull Boxes, Sheets 1 and 2
- LSP 93 Small Cell Street Lighting Poles, Sheets 1, 2, 3 and 4
- LSP 642 P.C. Concrete Pavement Repair, Sheets 1
- LSP 662 Cul-de-sac Joints - SHEET REMOVED

LSP 81 sheet 1

- Pull Box Notes modified

LSP 81 sheet 2

- Building Entrance – Fiber Access Added

LSP 93 sheet 1

- Notes and details modified
- Details 1, 2 and 3 moved to sheet 2, because Notes were expanded

LSP 93 sheet 2

- Details modified
- Details 9, 10, 11, 12, 13 moved to sheet 3
- Bearing Plate Anchor Bolts no longer used, Details 14 and 15 removed
- Pole and Luminaire Arm Data Table expanded for more poles and details

LSP 93 sheet 3

- Sheet added
- Details added
- Details modified from other sheets
- J Anchor Bolts added for consistency
- Type B Poles base cover added

LSP 93 sheet 4

- Sheet Added
- Details added for Type B Poles (P Street style poles)

LSP 642 sheet 1

- Notes modified (dowel bars)