

Site Supervisor Certification Requirements

1. All work sites where utility installations are conducted within the City's right of way requires at least one person on the job site that is "Site Supervisor" certified.
2. To acquire training for a "Site Supervisor", contact the City of Lincoln – Public Works and Utilities Department (402) 441-7711. Request to schedule a Site Supervisor Training time at least two days in advance of desired date and time.
3. Completion of approved test results, a Site Supervisor certification card will be mailed to the applicant. Also at the time of testing the applicant will be provided current copies of the City of Lincoln "Standard Specifications" and "Standard Plans".
4. The Site Supervisor Certification is valid for a one year period.
5. You may complete the Site Supervisor Test at the City's Annual Spring Workshop, normally conducted in March.
6. You may be asked by any city staff to provide the "Site Supervisor Card" while conducting work in the city right of way.
7. It shall be the applicant's responsibility to maintain a valid "Site Supervisor" certification.